





REDDING LOUNGE CHAIR






List of part			List of hardware		
		N.o of pcs			N.o of pcs
①		1	A		4
②		1	B		M8x45 4
③		1	C		M6x20 4
④		1	D		M6x30 2
⑤		1	E		Dia 6mm 1
⑥		1	F		Dia 4mm 1
⑦		1	G		5x40 10
			H		Φx20 4


Step 1



Step 2




Step 3



Step 4

Mo	Tu	We	Th	Fr	Sa	Su
1	2	3	4	5	6	7
⊗ 8	9	10	11	12	13	14
15	16	17	18	19	20	21
⊗ 22	23	24	25	26	27	28
29	30	31				

2-4 weeks/veckor



Tighten the screws regularly or if needed!

Efterspänn skruvarna regelbundet eller vid behov!