





ASSEMBLY INSTRUCTIONS

ITEM NO. - 1920848-01-0

PARTS LIST

P1	x1	P2	x3	P3	x3	A	x12	B	x9	C	x9	D	x9	E	x1
															
						M6x20	M6x20	M6xO.D.10	M6xO.D.15						#4

STEP-1




Diagram illustrating Step 1: Assembly of the leg base. Part E (Pin) is inserted into the flange P3. Part A (Screw) is inserted into the flange P3. The flange P3 is then attached to the leg P2.

STEP-2




Diagram illustrating Step 2: Assembly of the leg to the base. The leg assembly (P2, E, B, C, D) is attached to the base plate P1. A 50% load test is shown with a 50KG weight.

STEP-3




Diagram illustrating Step 3: Final assembly. The base plate P1 is shown with three legs attached. A 100% load test is shown with a 50KG weight.

LOADABILITY




Diagram illustrating the final assembled table. A 50KG weight is shown on the table surface.