





2195565-01-0 / 2195565-02-0 /  
2195565-03-0

A	B
	
x6	x6

02




Use a level ruler to ensure that the hole positions are level




18- $\varnothing 7$ \*50

03



04



05

