





Jotex



1



① X1



② X2



③ X2



④ X2

2



A: X12
M6X14mm



B: X1
5#




C: X2



D: X4
M3X10mm





E: X1





(Tools not included)


3




4







5



6



7



E: X1

8

