


BOSS DUVAR RAFI








This unit should be assembled by two persons.




ACCESSORY LIST

The necessary tools (not included)


A17 4x50 YHB Screw  44x	A16 Ø8 Peg  5x	A11 3,5x18 YHB Screw  5x	A06 TAPA 1. Color 2. Color  28x 16x	A19 L demir  5x
A18 5X70 YHB Screw  5x				

GENERAL VIEW




ASSEMBLY MANUEL

A17




02
Level



A17

A17

03
Level



ASSEMBLY MANUAL

