



ASSEMBLY INSTRUCTION

MELFORT DINING TABLE






ROWICO

HOME



<p>1 x1</p>	<p>Ax8</p> <p>M8x60</p>
<p>2 x2</p>	<p>Bx8</p> <p>Ø8</p>
<p>3 x2</p>	<p>Cx8</p> <p>Ø8/Ø16</p> <p>Dx4</p> <p>Ø30</p>
<p>3 x2</p>	<p>E x1</p> <p>N5</p>



Note:
Improper use, improper assembly and mishandling may lead to defects/ cracks appearing.